



Penn Reel Parts list for Model: SSVi7500LC-US (1481275) and SSVi7500LC-EU (1482276) Spinfisher VI Long Cast Models

| KEY  | PUREFISHING | PENN PART        | DESCRIPTION                             | KEY  | PUREFISHING | PENN PART         | DESCRIPTION                                   |
|--|-------------|------------------|---|--|-------------|-------------------|---|
| NO   | NO.         | NO.              |   | NO   | NO.         | NO.               |   |
| 1  | 1494865     | 1-SSVi7500LC-US  | HOUSING, BODY ASSEMBLY (USA)            | 39A  | 1341524     | 39A-SSV7500LC     | SPOOL ADJUST WASHER                           |
| 1  | 1494866     | 1-SSVi7500LC-EU  | HOUSING, BODY ASSEMBLY (EUROPEAN)       | 39B  | 1341525     | 39B-SSV7500LC     | MAIN SHAFT WASHER                             |
| 1F   | 1419019     | 1F-SLA5500       | BODY SIDE SEAL                          | 39C  | 1259637     | 39C-7000AF        | MAIN SHAFT NUT                                |
| 1G   | 1419020     | 1G-SLA5500       | BODY SIDE SEAL LOCK PLATE               | 39D  | 1483228     | 39D-CFTi8000LC    | RUBBER PAD                                    |
| 1H   | 1418957     | 1H-SLA3500       | SCREW (7 REQUIRED)                      | 39E  | 1483229     | 39E-CFTi8000LC    | FIXING PLATE                                  |
| 2  | 1341498     | 2-SSV7500LC      | A/R BUTTON                              | 43   | 1259636     | 43-AF8000LC       | OSCILLATION SLIDER (CROSSWIND BLOCK)          |
| 2L   | 1494867     | 2L-SSVi7500LC    | SEAL FOR HOUSING BODY                   | <b>43A OCS.GUIDE/BLOCK PLATE - SEE ERROR NOTES PG3</b> |             |                   |   |
| 3  | 1341500     | 3-SSV7500LC      | A/R BUTTON SCREW                        | 43B  | 1276992     | 14-SSV6500LL      | O/S SLIDER RETAINER SCREW (2 REQUIRED)        |
| 4  | 1494868     | 4-SSVi7500LC     | A/R PAWL / LEVER                        | 43D  | 1122193     | 43D-7000AF        | OSCILLATION SLIDE BUSHING                     |
| 4A   | 1341502     | 4A-SSV7500LC     | A/R LEVER SEAL                          | 43E  | 1122192     | 43E-7000AF        | GUIDE PAWL                                    |
| 4B   | 1361929     | 4B-SSV7500LC     | A/R LEVER WASHER                        | 43F  | 1259623     | 43F-AF8000LC      | RIGHT GUIDE SHAFT                             |
| 5  | 1483180     | 5-CFTi8000LC     | A/R PAWL / LEVER SPRING                 | 43G  | 1494885     | 43G-SSVi7500LC    | WORM SHAFT                                    |
| 8  | 1494869     | 8-SSVi7500LC     | MAIN DRIVE GEAR                         | 43H  | 1377609     | 43H-BTLi8000LC    | WORM SHAFT BALL BEARING                       |
| 8A   | 1277146     | 8A-SSV7500       | SHIM, WASHER (FOR MAIN GEAR)            | 43J  | 1259620     | 43J-7000AF        | WORM SHAFT TOP RETAINER PLATE                 |
| 13   | 1347065     | 13-SSV7500LC     | CLICKER GEAR                            | <b>43L BUSHING - SEE ERROR NOTES ON PG3</b>            |             |                   |   |
| 15   | 1494870     | 15-SSVi7500LC    | HANDLE ASSEMBLY                         | 43M  | 1341534     | 43M-SSV7500LC     | WORM SHAFT SEAL                               |
| 15E  | 1494749     | 15E-SSVi6500LL   | HANDLE KNOB ONLY                        | 43Q  | 1259626     | 43Q-AF8000LC      | LEFT GUIDE SHAFT                              |
| 15P  | 1495539     | 15P-SSVi7500LC   | SUB-HANDLE ASSMEBLY (ARM ONLY)          | 43R  | 1259627     | 43R-AF8000LC      | REAR RETAINER PLATE                           |
| 19   | 1494871     | 19-SSVi7500LC    | PINION GEAR                             | 45   | 1494886     | 45-SSVi7500LC     | HOUSING / BODY COVER                          |
| 19A  | 1259612     | 19A-SSV7500LC    | PINION GEAR WASHER                      | 46   | 1381400     | 46-SSV7500LC      | HOUSING COVER SCREW (4 REQUIRED)              |
| 19C  | 1385683     | 19C-CLA8000      | PINION GEAR POM BUSHING                 | 46T  | 1494762     | 46T-SSVi6500LL    | SCREW, FOR HANDLE KNOB                        |
| 19D  | 1341509     | 19D-SSV7500LC    | WASHER                                  | 47   | 1494887     | 47-SSVi7500LC     | SPOOL ASSEMBLY (USA)                          |
| 20   | 1308090     | 20-CFT5000       | BALL BEARING (2 REQUIRED)               | 47   | N/A         | 47-SSVi7500LC-EU  | SPOOL ASSEMBLY (EUROPEAN)                     |
| 20B  | 1344681     | 20B-SSV7500      | BALL BEARING                            | 47B  | 1341538     | 47B-SSV7500LC     | SPOOL BAND                                    |
| 21   | 1494872     | 21-SSVi7500LC    | PINION BEARING RETAINER                 | 47D  | 1483213     | 47D-CFTi8000LC    | LINE CLIP                                     |
| 21A  | 1277044     | 21A-SSV5500      | SCREW, FOR PINION RETAINER (4 REQUIRED) | 47F  | 1259575     | 47F-7000AF        | LINE CLIP RETAINER                            |
| 21B  | 1494873     | 21B-SSVi7500LC   | COLLAR, FOR PINION BALL BEARING         | 47P  | 1494888     | 47P-SSVi7500LC-US | SPOOL (BARE SPOOL, NO OTHER PARTS) (USA)      |
| 21C  | 1494874     | 21C-SSVi7500LC   | O-RING, FOR BEARING RETAINER            | 47P  | 1494889     | 47P-SSVi7500LC-EU | SPOOL (BARE SPOOL, NO OTHER PARTS) (EUROPEAN) |
| 22   | 1381395     | 22-SSV7500LC     | ROTOR COVER SCREW                       | 47S  | 1494890     | 47S-SSVi7500LC    | SEAL  |
| 24   | 1494875     | 24-SSVi7500LC    | BAIL WIRE                               | <b>48 CLICK TONGUE PLATE - SEE ERRORS PG3</b>          |             |                   |   |
| 24C  | 1494753     | 24C-SSVi6500LL   | HANDLE KNOB CAP                         | 48D  | 1341546     | 48D-SSV7500LC     | SPOOL CLICKER SPACER RING                     |
| 25   | 1385663     | 25-CLA8000       | BAIL HOLDER (BAIL CAM)                  | 49   | 1259579     | 49-7000AF         | CLICK TONGUE SPRING                           |
| <b>27 ROTOR SEE NOTES PG3</b>                        |             |                  |   | 49A  | 1341547     | 49A-SSV7500LC     | SPOOL CLICKER SPRING SCREW                    |
| 27A  | 1494877     | 27A-SSVi7500LC   | BAIL PIVOT COVER                        | 51   | 1378418     | 51-BTLi7000LC     | DRAG WASHER RETAINING RING                    |
| 27B  | 1494878     | 27B-SSVi7500LC   | LINE GUARD HOLDER                       | 52   | 1494891     | 52-SSVi7500LC-US  | DRAG KNOB ASSEMBLY (USA)                      |
| 27C  | 1341516     | 27C-SSV7500LC    | LINE GUARD HOLDER SCREW                 | 52   | 1494892     | 52-SSVi7500LC-EU  | DRAG KNOB ASSEMBLY (EUROPEAN)                 |
| 27D  | 1494879     | 27D-SSVi7500LC   | LINE GUARD (ON LINE ROLLER SIDE)        | 53S  | 1483237     | 53S-CFTi8000LC    | DRAG KNOB SEAL                                |
| 27E  | 1381396     | 27E-SSV7500LC    | SCREW                                   | 56   | 1341550     | 56-SSV7500LC      | DRAG FRICTION WASHER (2 REQUIRED)             |
| 28   | 1494880     | 28-SSVi7500LC    | BAIL TRIP LEVER                         | 57   | 1341551     | 57-SSV7500LC      | KEYED METAL DRAG WASHER (2 REQUIRED)          |
| 28D  | 1494881     | 28D-SSVi7500LC   | ROTOR BRAKE                             | 95B  | 1419114     | 95B-SLA7500       | ROTOR NUT LOCKING PLATE / COVER               |
| 28E  | 1341520     | 28E-SSV7500LC    | BRAKE RETAINER PLATE                    | 98   | 1259618     | 98-7000AF         | CLUTCH / SLEEVE ASSEMBLY                      |
| 28S  | 1277054     | 28S-SSV5500      | SCREW, FOR ROTOR BRAKE (3 REQUIRED)     | 98A  | 1361930     | 98A-SSV7500LC     | CLUTCH ASSEMBLY SPRING                        |
| 31   | 1277055     | 31-SSV5500       | BAIL ARM SCREW (2 REQUIRED)             | <b>132 LINE ROLLER COLLAR - SEE ERRORS PG3</b>         |             |                   |   |
| 32   | 1494882     | 32-SSVi7500LC    | BAIL SPRING                             | 226  | 1494893     | 226-SSVi7500LC    | REAR COVER                                    |
| 34   | 1389667     | 34-CLA8000       | BAIL ARM                                | 226A   | 1341553     | 226A-SSVi7500LC   | REAR COVER SCREW                              |
| 34C  | 1277164     | 34C-SSV7500      | PIVOT ARM                               | 226B   | 1341554     | 226B-SSVi7500LC   | BODY REAR SEAL                                |
| <b>35 LINE ROLLER - SEE ERROR NOTES PG3</b>          |             |                  |   | 231  | 1259624     | 231-AF8000LC      | CROSSWIND OSCILLATION GEAR                    |
| <b>35A LINE ROLLER BUSHING - SEE ERROR NOTES PG3</b> |             |                  |   | 231E   | 1259622     | 231E-7000AF       | SLOW O/S GEAR                                 |
| <b>35B BALL BEARING - SEE ERROR NOTES PG3</b>        |             |                  |   | 231F   | 1259621     | 231F-7000AF       | SLOW O/S GEAR PIN                             |
| 36   | 1422399     | 36-SLA9500       | LINE ROLLER SCREW                       | 231G   | 1277070     | 43B-SSV5500       | SCREW   |
| 36B  | 1417809     | 36B-CLA6000      | LOCK WASHER                             | 233A   | 1419118     | 233A-SLA7500      | HANDLE CAP ASSEMBLY                           |
| 38   | 1419103     | 38-SLA7500       | ROTOR NUT                               | 233C   | 1419076     | 233C-SLA5500      | HANDLE CAP SEAL                               |
| <b>38A ROTOR NUT SCREW SEE PG3</b>                   |             |                  |   |  |             |                   |   |
| 38E  | 1302502     | 232B-SSV3500     | O'RING, FOR BEARING RETAINER            |  |             |                   |   |
| <b>38F SEAL RING - SEE ERRORS PG3</b>                |             |                  |   |  |             |                   |   |
| 39   | 1494883     | 39-SSVi7500LC-US | MAIN SPOOL SHAFT (USA)                  |  |             |                   |   |
| 39   | 1494884     | 39-SSVi7500LC-EU | MAIN SPOOL SHAFT (EUROPEAN)             |  |             |                   |   |

### MYSTIC REEL PARTS REVISION!

NOTE: Many of www.mysticparts.com schematics include changes that were either made by Penn, or errors found and corrected by our parts dept.  
MRP Ver 102118 (Based on Penn's Rev. 01 , 19-11-2018)

### PART ERROR CORRECTED WHEN DISSECTING REEL FOR REVIEW

| KEY  | PUREFISHING   | PENN PART     |  |
|------|---|---------------|--|
| NO   | NO.   | NO.           | DESCRIPTION  |
| 38A  | 1277063   | 38A-SSV5500   | ROTOR NUT LOCK PLATE SCREW (Sheet Metal Threading) INCOMPATIBLE! |
| USE: | 1385669   | 38A-CLA8000   | ROTOR NUT LOCK PLATE SCREW FLAT PAN HEAD (3 REQUIRED)            |
|      | REV00 ERROR   |               |  |
| 38F  | 1419080   | 38F-SLA7500   | SEAL RING (FOR ROTOR MAIN SHAFT)                                 |
|      | REV00 ERROR typo as 39F-SLA7500 which doesn't exist   |               |  |
| 43L  | 1341533   | 43L-SSV7500LC | WORM SHAFT LOWER BUSHING (DOES NOT FIT!) ERROR!                  |
| USE: | 1122132   | 43L-7000AF    | WORM SHAFT LOWER BUSHING (3 REQUIRED)                            |
|      | REV00 ERROR (MEASUREMENTS CONFIRMED USE THIS) SSVi5500LC, SSVi6500LC and SSVi7500LC reels   |               |  |
| 43A  | 1259635   | 43A-7000AF    | OSCILLATION SLIDER GUIDE (CROSSWIND PLATE)                       |
|      | Above is info on REV00 for the 43A<br>On REV01 Penn lists part 43A-AF7000LC but uses the 7digit# for the 43A-7000AF<br>43A-7000AF is what was found in reels taken apart by MRP<br>There does not appear to be a 43A-AF7000LC in the Penn USA system at this time |               |  |
| 48   | 1259577   | 48-7000AF     | CLICK TONGUE   |
|      | REV00 & REV01 HAVE TYPO AS 13-7000AF WHICH DOESN'T EXIST  |               |  |

### ERRORS: LINE ROLLER SYSTEM

When taking the SSVi7500LC apart, we found the numbers for the roller parts were all using 6500HS size  
This is incorrect, the 6500HS sized parts would NOT fit, too small

|      |   |                  |   |
|------|---|------------------|---|
| 35   | 1457403   | 35-SLAiii6500HS  | LINE ROLLER (ERROR TOO SMALL DOES NOT MATCH REEL)         |
| USE: | 1457805   | 35-SLAiii8500HS  | LINE ROLLER (FOUND IN REEL)                               |
|      | REV00 AND REV01 ERROR WITH PART NUMBER  |                  |   |
| 35A  | 1457404   | 35A-SLAiii6500HS | LINE ROLLER BUSHING (ERROR TOO SMALL DOES NOT MATCH REEL) |
| USE: | 1457806   | 35A-SLAiii8500HS | LINE ROLLER BUSHING (FOUND IN REEL)                       |
|      | REV00 AND REV01 ERROR WITH PART NUMBER  |                  |   |
| 35B  | 1377606   | 35A-BTLii8000LC  | LINE ROLLER BALL BEARING (corrected REV01)                |
|      | REV00 There was a typo that had this part as 35B-BTLii8000LC which does not exist |                  |   |
| 132  | 1457405   | 132-SLAiii6500HS | LINE ROLLER COLLAR (ERROR TOO SMALL DOES NOT MATCH REEL)  |
| USE: | 1457807   | 132-SLAiii8500HS | LINE ROLLER COLLAR (FOUND IN REEL)                        |
|      | REV00 AND REV01 ERROR WITH PART NUMBER  |                  |   |

### OPTIONAL MODDING:

If desired, anywhere in the reel that the 43L bushing is used, you could sub to the 43H ball bearing, they are the same measurements and thickness.  
Or you could intermix 43L and 43H in any grouping, but it is recommended that you keep a 43H in the 43H location.

SSVi5500LC, SSVi6500LC and SSVi7500LC reels

should I add modding notes to the 43h and 43l screens online and cross link them?

### FOUND IN ALL THE SSVi LC MODELS BUT NOT ON REV 0 OR REV 01

|       |   |                |  |
|-------|---|----------------|--|
| 43S** | ??  | 43S-SSVi5500LC | SHIM, EARRED SHIM (VARYING QTY IN THE REELS) |
|       | ** NOT ON ON ORIG SCHEMATICS, FOUND UNDER THE 43J U-shaped collar (SOME REELS HAD NONE AT ALL OR JUST |                |  |

### ROTOR INFO:

| KEY | PUREFISHING | PENN PART      |  |
|-----|-------------|----------------|--|
| NO  | NO.         | NO.            | DESCRIPTION  |
| 27  | 1494876     | 27-SSVi7500LC  | ROTOR (METAL BASE, GRAPHITE TOP, COMES AS A UNIT)              |
| 27H | ??          | 27H-SSVi7500LC | ROTOR TOP (GRAPHITE)   |
| 38A | 1385668     | 38A-CLA8000    | ROTOR TOP SCREWS (1 REQUIRED) (IDENTIFIED & CONFIRMED IN REEL) |

We have assigned temp part number for 27H

27H and these 38A are not shown on the schematic

They appear to be considered part of the rotor at early schematic revisions

Penn has not assigned part numbers to the top

We will update this if Penn revises their schematic and gives us a different #

REV00 ERROR